



## Orsett BA Training Centre Case Study

**Details:** Installation of four standard free standing drying systems within the existing Drying Room.

**Comments:** "Steam burns caused by wearing damp fire kit are a major Health & Safety risk when carrying out live fire training. Training in wet kit can also lead to skin inflammations caused by the damp material rubbing against the skin. With TOP TROCK drying systems, fire kit can be dried during the debrief, ensuring it is dry before the next training exercise".

