



Burnham Fire Station Case Study

- Details:** Installation of standard free standing mobile drying system within the Appliance Bay as part of a full station refurbishment.
- Comments:** "It took 3 to 4 days to dry fire kit in the old drying cupboard and the station was often "off the run" as both sets of our kit were wet. We had to dry boots and gloves directly on the radiator. The TOP TROCK system is very fast especially for boots and gloves".



Burnham Fire Station



Before TOP TROCK Drying System



After the installation of TOPTROCK Drying System