



Coggeshall Fire Station Case Study


- Details:** Installation of standard free standing mobile drying system within the Appliance Bay as part of a full station refurbishment.
- Comments:** "Fire kit is now dried within the appliance bay rather than taking dirty wet kit into the rec room and drying it over the radiators".



Coggeshall Fire Station



Before TOP TROCK Drying System



After the installation of TOP TROCK Drying System

