



Loughton Fire Station Case Study

Details: Installation of standard free standing mobile drying system within the Drying Room as part of a full station refurbishment and heating upgrade.

Comments: "We had to dry boots and gloves on the heating pipework and it took 3 - 4 days to dry fire kit in the old drying room".



Loughton Fire Station



Before TOP TROCK Drying System



After the installation of TOP TROCK Drying System

